



the future is safer with altro


altro

Altro Aquarius™


Safety flooring / Suelos de seguridad / Sicherheitsbodenbelag



New colours



Cygnet AQ2004
WR287 / A1M79 / LRV 46




NEW Sea Snail AQI2024
WR370 / A1M370 / LRV 50



NEW Iguana AQ2021
WR297 / A1M20 / LRV 41



Swan AQI2012
WR291 / A1M1 / LRV 75




Puffin AQI2005
WR287 / A1M79 / LRV 46



Dragonfly AQ2001
WR292 / A1M292 / LRV 33




Vole AQ2010
WR289 / A1M265 / LRV 43



Treefrog AQI2003
WR293 / A1M271 / LRV 33



Walrus AQ2007
WR261 / A1M81 / LRV 29




Blue Penguin AQI2002
WR288 / A1M71 / LRV 24



Terrapin AQI2009
WR289 / A1M265 / LRV 40



NEW Gosling AQI2023
WR369 / A1M369 / LRV 59




Tern AQI2008
WR261 / A1M81 / LRV 31



NEW Newt AQ2022
WR368 / A1M368 / LRV 10




Otter AQI2006
WR290 / A1M239 / LRV 26



Salamander AQI2011
WR294 / A1M294 / LRV 41



Hippo AQI2013
WR301 / A1M82 / LRV 11



Mallard AQI2015
WR302 / A1M302 / LRV 13



Coral Crab AQI2014
WR300 / A1M42 / LRV 14



Spoonbill AQI2016
WR303 / A1M303 / LRV 11

Codes: WR = weld rod, A1M = mastic, LRV = light reflectance value

Códigos: WR = Cordón de soldadura, A1M = Mástique, LRV = Valor de reflectancia de la Luz

Abkürzungen: WR = Schweißschnüre, A1M = Altro mastic dichtmasse, LRV = Lichtreflexionswert



Altro Aquarius™

Typical Applications:

Bathrooms. Showers. Changing rooms. Swimming pool surrounds. Saunas.

Zonas de instalación recomendadas:

Aseos. Duchas. Vestuarios. Alrededores de piscinas. Saunas.

Typische Anwendungsbereiche:

Badezimmer. Duschen. Umkleieräume. Schwimmbadränder. Saunen.



Slip resistance / Resistencia al deslizamiento / Rutschfestigkeit

Tested with / Testado con / Getestet mit:

Soapy water / Agua con jabón / Seifenwasser

Shower gel / Gel de ducha / Duschgel

Talcum powder / Polvos de talco / Talkumpuder

Conditioner / Suavizante / Haarspülung

Glycerine / Glicerina / Glycerin

Looks great with / Resultados espectaculares con / Harmoniert besonders in Kombination mit:

Altro Whiterock Satins™ / Altro Whiterock Chameleon™ / Altro Walkway™ 20

i Technical information / Información técnica / Technische Informationen

Flooring type Tipo de pavimento Belagsart	Slip resistance Resistencia al deslizamiento Rutschsicherheit	Thickness Espesor total Gesamtdicke	Weight Peso Flächengewicht	Roll dimensions Dimensiones del rollo Rollenabmessungen	Fire performance Reacción al fuego Brandverhalten
EN 13845 EN 13553	TRRL EN 13845 EN 13893 DIN 51130 DIN 51097	EN 428	EN 430	EN 426	EN 13501-1 EN ISO 9239-1 EN ISO 11925-2
Safety flooring Suelo de seguridad antideslizante Sicherheitsbodenbelag	≥ 50 (slider 96) ESf & ESb DS R11 Class B	2 mm	2.6 kg/m ²	2 m x 20 m - 40 m ²	Bfl s1 ≥ 8kW/m ² pass, conforme, bestanden
i For further technical information please visit www.altro.com / www.asf.com.au Si desea obtener más información técnica, visite www.altroscandess.com Weitere technische Informationen finden Sie auf unserer Website www.altro.de			Patent No. GB 2 462 167 Patent No. GB 2 496 644		



g Sustainability / Sostenibilidad / Nachhaltigkeit

Altro are the first safety flooring manufacturer to recycle traditional safety flooring in-house



A+ BRE generic green guide rating for safety flooring, full details available at www.thegreenguide.org.uk



+44 (0) 1462 707 700

+34 91 549 5230

+61 3 9764 5666

www.altro.com

www.altroscandess.com

www.asf.com.au

enquiries@altro.com

suelos@altroscandess.com

info@asf.com.au



CE

EN14041
0120
GB06/72664

Manufactured by:
Altro Ltd, Works Road
Letchworth Garden City
SG6 1NW, United Kingdom

EN13845

i Installation and Maintenance

All Installations in accordance with Altro safety flooring instructions and local codes of practice. Please refer to Altro cleaning card for maintenance advice. Failure to install and maintain Altro flooring in accordance with installation instructions can affect its performance and slip resistance. Floors should be protected from other trades and thoroughly cleaned before handover.

Traffic stain can be caused by oil residue, certain cleaning agents, asphalt and anti-oxidants in some types of rubber.

Caution

ketone / aromatic solvents. Please contact Altro for further technical advice regarding staining and chemical resistance. Certain chemicals may cause staining of vinyl.

Altro Limited a company certified by SGS to ISO 9001 and ISO 14001.

Light Reflectance Values measured in accordance with BS8493:2008. Exact material match with samples cannot be guaranteed. No podemos garantizar que el material del suelo de seguridad coincida exactamente con el de las muestras. Eine exakte Übereinstimmung des materials mit mustern kann nicht garantiert werden. All information is correct at the time of print and is subject to change without prior notice.

